2. Battery overcharging (regulated voltage too high).