


Remove the front cover from the combination meter case.



Remove the six terminal screws and tachometer/indicator unit.



Remove the screw and trip meter knob.



Remove the two speedometer gearbox screw, then remove the speedometer unit.

